PLUXO
MOUNTING INSTRUCTION
03-12-2015

2.0 LED

LED 2x8W | 220-240V | 50-60Hz | COB 2-step | incl. PS | phase-cut dim

CE ⏚ IP20 960°C ⊡0,3m ℗ ■ ⟋36° ↻ 45°/45° ↻ 10°

	white texture	142264W_
	silver / grey	142264S_
	black texture	142264B_

LIGHT COLOUR
2700K	>80CRI	2x480lm	2
3000K	>80CRI	2x480lm	4

2.0 PAR16

◁ 2xPAR16 max. 50W | GU10 | 220-240VAC | 50-60Hz

CE ⏚ IP20 960°C ⊡0,9m ■ ↻ 45°/45° ↻ 10°

|		
	white texture	142220W0
	silver / grey	142220S0
	black texture	142220B0

OPTIONAL
for PAR16 lamps see our catalogue

ceiling base dimensions

2.0 LED

① ↑

⑤ ↑

⑥ ↑

2.0 PAR16

① ↑

⑤ ↑

⑥ ↑

DIMENSIONS

95   190
116
ø68
2.0 LED

95   190
116
ø68
**2.0 PAR16**

MOUNTING INSTRUCTION

① Mount the ceiling base to the ceiling with screws.

POWER CONNECTION

② Connect per PLUXO fixture the earthing wire to the slider on the ceiling base.

PARALLEL CONNECTION

220-240V
N ⏚ L   fixture 01   fixture 02   fixture ..
                L N   L N   L N

③ Connect the LED modules to the terminal blocks on the fixture.

④ Connect the PLUXO fixtures to each other with the included through wiring cables.

⑤ Click the PLUXO on the ceiling base.

⑥ Insert the lamp and fix with spring.

PLUXO
POWER CONNECTION
03-12-2015

LED modules

DRIVER

DRIVER

220-240VAC

N
L
PE *

PAR16

220-240VAC

N
* PE
L

POWER CONNECTION

* Connect per PLUXO fixture the earthing wire to the slider on the ceiling base.

LED module

Connect the LED modules to the terminal blocks on the fixture. Now the LED modules are connected to the drivers. Connect the input of the drivers to 220-240VAC like mentionned on the illustration.

PAR16

Connect the PAR16's directly to 220-240VAC like mentionned on the illustration.

PLUXO
HOW TO PUT CONNECTOR IN CEILING BASE
03-12-2015

HOW TO PUT CABLE & CONNECTOR IN THE CEILING BASE?

For example we take the LED version.

① Unpack the fixture from the packaging. With the LED version you'll see that the connector is placed at the visible side of the fixture.

② Unscrew the screws that hold the power supply at it's place.

③ Remove the power supply so you have enough space to remove the rubber gasket.

④ Remove the small rubber gasket.

①

Connector from power supply.

②

③

④

www.weverducre.com

WEVER & DUCRÉ
LIGHTING

INSTALLATION
INSTRUCTIONS
PAGE 3/4

PLUXO
HOW TO PUT CONNECTOR IN CEILING BASE
03-12-2015

Connector from power supply.

⑤

⑥

⑦

⑧

⑨

⑩

HOW TO PUT CABLE & CONNECTOR IN THE CEILING BASE?

⑤ Pull the cable with connector, from the power supply, upwards through the opening.

⑥ Connect the LED module on the fixture.

⑦ Pull the cable with connector, from the LED module, upwards through the opening.
Keep in mind that there are labels attachted to this cable. Also pull these labels through the opening.

⑧ Connect both connectors to each other.
(LED module - power supply)

⑨ Put the rubber gasket back on the wire.

⑩ Fixate the rubber gasket back in the hole of the fixture.

Don't forget to place the power supply back on the fixture by screws.