
TORCO ON TRACK

17-Mar.-2017



DIMENSIONS



MOUNTING INSTRUCTION

- 1) Make sure the knob is on the OFF position.
- 2 Push the fixture into the track.
- 3 Turn the knob to the Lock position.
- 4 Select the phase.

The light source of the integrated LED is not replaceable; When the light source reaches its end of life the whole luminaire shall be replaced.



Caution, risk of electric shock



INSTALLATION INSTRUCTIONS